Support for Host Print Transform

Firmware version 4.73a is required to support TN5250-HPT functionality. HPT is only supported on the 405 platform or version 4.xx. Other platforms such as versions 1.xx, 2.xx, and 3.xx do not support HPT and will require using the Anynet protocol.

Support for HPT will also require using the most current version of the Configuration Utility 4.73 or newer.

Telnet will create a printer with HPT enabled and a Manufacturer Make and Model of HP4000. You will need to change the Model after the printer has been created. If printing to a Label printer, you will also need to specify the Work Station Customizing Object (WSCST) and Library.